EXHIBIT 5

09-50026-mg Doc 13027-5 Filed 12/16/14 Entered 12/16/14 17:20:07 Exhibit 5

TECHNICAL ASSISTANCE CENTER

**** GM RESTRICTED ****

Privacy

Case No: 06944131 VIN:

Date Opened: 20031119 Model Year: 2003

Date Closed: 11/19/2003 Model Series: AF

Dealer Code: ?121731 Mileage: 027275

Dealer Name: Saturn Of Toledo, InToledo Dealer State: OH

Dealer Phone: 4198419070 Division: Saturn - GM

SYMPTOM ABSTRACT--- NO STALL VEHICLE VEHICLE STALL NO CODES

RESOLUTION ABSTRACT- CUSTOMER CONCERN NOT DUPLICATED - EMISSIONS

UCC CODE 1-----

UCC-1 DESCRIPTION--- Engine

UCC CODE 2-----

UCC-2 DESCRIPTION---

UCC CODE 3-----

UCC-3 DESCRIPTION---

11/19/2003 15:57:17 SBD Template - SALISBURY

Tech states vehicle came in with an intermittent stall no codes.

Tech states he cannot duplicate condition.

Tech state if he turns the ignition key backwards slightly the vehicle

dies.

Tech looking for knowns.

Advised tech to inspect ignition switch connector and terminal tightness

for any issues.

Asked tech to call back with update.

11/19/2003 15:57:17 History - SALISBURY

11/19/2003 16:22:06 XANDERS - Closing -

Tech checked ign switch connector - good. Tech can duplicate and can

see the key rotating to off position.

Advised tech engineering is working on issue - no current fixes

available.